



## **Future Coat Technology**

### **CUPRA GLOW**

**CUPRA GLOW for brass and copper products**

**Purpose and usage**

Cupra glow is used to remove copper stain from acid copper plated products to get extra finish and bonding between other plating process.

**Versatile: it may be used on brass copper**

**High appearance**

**Remove all type of stain**

**Remove the effect of Blue and Black dye stains after acid copper plating**

**Mixes completely with DM water**

**Free rinsing**

**Non toxic**

**HOW TO USE CUPRA GLOW:**

**Equipment:**

P.P.tank and heating coils are recommended fume extraction should be provided to control fumes from hot solutions.

**As cupra glow:**

High grade bright and uniform finish. It can be used in a swilling bath with addition on 10 ml/ltr cupra glow and carry forward with hot water swill to remove excess chemical on the plated product and then two cold water swill and then to the next plating process. It can be used as for bright dib before gold or silver plating

		<b>OPTIMUM</b>
<b>CUPRAGLOW</b>	<b>5 TO 15ML</b>	<b>10 ML</b>
<b>TEMPERATURE</b>	<b>50° TO 60°</b>	<b>55°ML</b>
<b>TANK</b>	<b>P.P.TANK</b>	